

1. You should never work on energized electrical equipment alone.
 - a. True
 - b. False
2. You may be severely shocked (complete an electric circuit through your body), if you stand on a damp or metal floor while working on an electrical device.
 - a. True
 - b. False
3. Current levels as low as 1mA can be sensed by the human body.
 - a. True
 - b. False
4. Workplaces that are not covered by the occupational health and safety act (OHSA) are:
 - a. Seneca College.
 - b. Airlines and airports.
 - c. Banks.
 - d. b and c.
5. The rights of the workers under the occupational health and safety act (OHSA) are:
 - a. Right to know about hazards.
 - b. Right to refuse dangerous work.
 - c. Right to participate in identifying and resolving health and safety issues in the workplace
 - d. a and b
 - e. a, b and c
6. The worker must wear protective equipment that his employer provides.
 - a. True
 - b. False
7. Under OHSA, the supervisor must:
 - a. Advise the worker where the washrooms are.
 - b. Advise the worker of the existence of potential hazards in the workplace.
 - c. Advise the worker where his/her office is.
 - d. All of the above.
8. Duties of the worker under the occupational health and safety act are:
 - a. Work in compliance with the provision of the occupational health and safety act.
 - b. Come to work on time.
 - c. Wear protective equipment that is provided by the supervisor
 - d. a and c
 - e. All of the above.
9. A supervisor can be charged personally for a violation of the occupational health and safety act.
 - a. True
 - b. False.